AQUELON HYDRATION · ACCESSORIES

Topserw 142.700.238

Repair kit



Repair kit needed in case of damage or failure of the activation button.

KEY FEATURES

- For damage or failure of the activation button

SPECIFICATIONS

Product code	142.700.238

DOCUMENTS AND QUOTES

- Product page, photos and related models: aquelon.com/products/topserw-142-700-238
- Catalogues, certificates and installation guides: aquelon.com/library
- Priced quote within one working day: aquelon.com/quote · sales@aquelon.com · +971 4 501 1360 · WhatsApp +971 58 576 3023

Manufactured by Topserw. Supplied in the GCC by Aquelon. Data from the manufacturer's published documentation, issued 8 November 2026; confirm against the manufacturer's current data and drawings before construction or ordering. Source: Topserw manufacturer documentation